Oil Field Environmental Incident Summary

Responsible Party: Oasis Petroleum

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: OASIS 5301 13-24 CTB

Field Name: BAKER Well File #:

 Date Incident:
 12/16/2013
 Time Incident:
 1500
 Facility ID Number:
 222100-01

 County:
 MCKENZIE
 Twp:
 153
 Rng:
 101
 Sec:
 12
 Qtr:
 SE SW

Location Description:

Submitted By: Dan Grafton Received By:

Contact Person:

1001 FANNIN STE 1500 HOUSTON, TX 77002

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

	Spilled	Units	Recovered	Units
Oil	10	barrels	9	barrels
Brine	0	barrels	0	barrels
Other	0	barrels	0	barrels

Description of Other Released Contaminant:

oil

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Areal Extent:

Followup Units

Potential Environmental Impacts:						
Action Taken or Planned:						
Valve replacemen	ıt					
Wastes Disposal Location:						
Agencies Involved:						
Undetee						
Updates						
Date: 12/18/2013	Status: Reviewed - Assigned to Other Agency	Author: Stockdill, Scott				
Updated Oil Volu	ume:					
Updated Salt Water Volume:						
Updated Other V	olume:					
Updated Other C	Contaminant					
Notes:						
According to the summary, this incident remained on location. NDIC retains oversight.						